	Туре	L #	Hits	Search Text	DBs
1	BRS	L1	1277	blind near2 fastener	USPAT; US-PGPUB; EPO; JPO; DERWENT
2	BRS	L2	308	1 and (sens\$5 detect\$5 transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
3	BRS	L4	4	3 and (compress\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
4	BRS	L5	3	4 and (deform\$6 bend\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
5	BRS	L7	9	"4314481"	USPAT; US-PGPUB; EPO; JPO; DERWENT
6	BRS	L6	10	"5661887"	USPAT; US-PGPUB; EPO; JPO; DERWENT
7	BRS	L8	38	'0039718''	USPAT; US-PGPUB; EPO; JPO; DERWENT
8	BRS	L11	619	Mauer.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT
9	BRS	L12	6	11 and (piezo\$8)	USPAT; US-PGPUB; EPO; JPO; DERWENT
10	BRS	L13	6	12 and (compress\$5 deform\$6 bend\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
11	BRS	L10	6	9 and (sens\$5 detect\$5 transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
12	BRS	L9	6	6 and (piezo\$8)	USPAT; US-PGPUB; EPO; JPO; DERWENT
13	BRS	L14	9	6 and (compress\$5 deform\$6 bend\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
14	BRS	L15	6	14 and (piezo\$8)	USPAT; US-PGPUB; EPO; JPO; DERWENT
15	BRS	L16	6	15 and (sens\$5 detect\$5 transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
16	BRS	L17	197252	piezo\$8	USPAT; US-PGPUB; EPO; JPO; DERWENT
17	BRS	L18	115611	17 and (sens\$5 detect\$5 transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
18	BRS	L19	11	18 and (blind near4 tool)	USPAT; US-PGPUB; EPO; JPO; DERWENT
19	BRS	L20	8	19 and (compress\$5 deform\$6 bend\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
20	BRS	L21	23	"4401134"	USPAT; US-PGPUB; EPO; JPO; DERWENT

_	Time Stamp	Comments	Error Definition	Erro
1	2004/08/30 13:38			0
2	2004/08/30 13:45			0
3	2004/08/30 13:40			0
4	2004/08/30 13:51			0
5	2004/08/30 13:43			0
6	2004/08/30 13:45			0
7	2004/08/30 13:49			0
8	2004/08/30 13:49			0
9	2004/08/30 13:50			0
10	2004/08/30 13:57			0
11	2004/08/30 13:57			0
12	2004/08/30 13:56			0
13	2004/08/30 14:05			0
14	2004/08/30 13:56			0
15	2004/08/30 13:56			0
16	2004/08/30 14:05			0
17	2004/08/30 14:05			0
18	2004/08/30 13:57			0
19	2004/08/30 13:59			0
20	2004/08/30 14:02			0

	Туре	L#	Hits	Search Text	DBs
21	BRS	L22	6	"995518"	USPAT; US-PGPUB; EPO; JPO; DERWENT
22	BRS	L23	0	22 and piezo\$8	USPAT; US-PGPUB; EPO; JPO; DERWENT
23	BRS	L24	4	21 and piezo\$8	USPAT; US-PGPUB; EPO; JPO; DERWENT
24	BRS	L25	7	"1382406"	USPAT; US-PGPUB; EPO; JPO; DERWENT
25	BRS	L26	0	25 and piezo\$8	USPAT; US-PGPUB; EPO; JPO; DERWENT
26	BRS	L27	11665	blind.clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
27	BRS	L28	185	27 and piezo\$8	USPAT; US-PGPUB; EPO; JPO; DERWENT
28	BRS	L29	107	28 and (compress\$5 deform\$6 bend\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
29	BRS	L30	76	29 and (sens\$5 detect\$5 transducer measur\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
30	BRS	L31	21	30 and (tool)	USPAT; US-PGPUB; EPO; JPO; DERWENT
31	BRS	L3	4	2 and (piezo\$8)	USPAT; US-PGPUB; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Erro rs
21	2004/08/30 14:01			0
22	2004/08/30 14:02			0
23	2004/08/30 14:03			0
24	2004/08/30 14:05			0
25	2004/08/30 14:03			0
26	2004/08/30 14:05			0
27	2004/08/30 14:05			0
28	2004/08/30 14:05			0
29	2004/08/30 14:05			0
30	2004/08/30 14:05			0
31	2004/08/30 14:07			0